


PC BOARD

WOW AND FLUTTER

1. Connect the wow and flutter meter to TPF on the control PCB ass'y.
2. Set the speed selector to 33 1/3 rpm.
3. Play back the part of 3 kHz in the test record.
4. Turn the trimming pot SC-1 GAIN so that the meter indicate the minimum deflection.

▼ REAR CONNECTION (X25-1550-xx) Components side view



Q201 : 2SC945(Q,P)
 Q202 : 2SD882(R,Q)
 IC201,202 : TA7136P
 D201 : W06B

2SC945



2SD882



TA7136P

